

Work Order ID 155991

Thursday, January 19, 2017 11:37:03 AM

155991



Page 1

Item ID: D4030-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 2/1/2017 Req'd Qty: 1.00 ***1*** Customer:

Reference:

Approvals: Process Plan:  Date: JAN 19 2017 Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4030	D								
100	Pick Kit	0.00							
100									
Packaging	Memo	0.00							FEB 09 2017 
Packaging									
110	Assemble as per dwg	0.00							
110									
HandFinish	Memo	0.16							
Hand Finishing									
120	QC5- Inspect part completeness to step on W/O	0.00							
120									
QC	Memo	0.00							
Quality Control									 FEB 14 2017

Picklist Print

Thursday, January 19, 2017 11:37:25 AM

Page 1
/9

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A new issue DD 10.03.23 verified by:EC IPP Rev:B as
per dwg revB DD 10.04.20 verified by:EC IPP Rev:C as per dwg
revC DD 10.08.18 verified by:EC IPP Rev D 12.03.27 per NCR12-
1239 EC verified by:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2530 *D2530* Handle Weldment		Manufactured	No			100	Each	19.0000	1	1		FEB 09 2017	DAS 6 9-89

Location	Loc Qty	Loc Code
ST379	11	
151699	3	
152175	8	
ST389	8	
152748	8	

D2535 *D2535* Spring		Manufactured	No			100	Each	27.0000	2	2		FEB 09 2017	DAS 6 9-89
-----------------------------------	--	--------------	----	--	--	-----	------	---------	---	---	--	-------------	------------------

Location	Loc Qty	Loc Code
ST008	27	
148592	2	
152351	25	

D2537 *D2537* Bushing		Manufactured	No			100	Each	64.0000	2	2			DAS 6 9-89
------------------------------------	--	--------------	----	--	--	-----	------	---------	---	---	--	--	------------------

Location	Loc Qty	Loc Code
ST008	64	
148918	14	
152293	30	
154171	20	

FEB 09 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
BAG 3 3 EAO 3								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER :							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Page 2

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

D3913-041 Manufactured No

100 Each

0.0000

1

1

**

FEB 09 2017

DAS
6
9-89

D3913-041

Long Basket Base Assembly, 350

D3914-041

Manufactured No

100 Each

0.0000

1

1

**

FEB 09 2017

DAS
6
9-89

D3914-041

Long Basket Lid Assembly (350)

D3917-3

Manufactured No

100 Each

41.0000

6

6

**

FEB 09 2017

DAS
6
9-89

D3917-3

Washer

Location

Loc Qty

Loc Code

ST058

41

152988

41

100 Each

39.0000

2

2

**

FEB 09 2017

DAS
6
9-89

D3953-3

Manufactured No

D3953-3

Gas Spring Stud, Lid

Location

Loc Qty

Loc Code

ST062

19

148400

11

152309

8

ST064A

20

153037

10

154178

10

100 Each

21.0000

2

2

**

FEB 09 2017

DAS
6
9-89

D3953-7

Manufactured No

D3953-7

Spring Spacer

Location

Loc Qty

Loc Code

ST062

21

151089

21

100 Each

21.0000

2

2

**

Thursday, January 19, 2017 11:37:26 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Page 3

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

D3953-9 Manufactured No

100 Each 27.0000 2 2

D3953-9

Gas Spring Washer

**

FEB 09 2017

DA
6
8-89

Location

Loc Qty

Loc Code

ST062

27

145912

27

2

D3953-17 Manufactured No

100 Each 41.0000 2 2

D3953-17

Gas Spring Spacer

**

FEB 09 2017

DAS
6
8-89

Location

Loc Qty

Loc Code

ST062

26

149542

2

152231

24

ST064A

15

153987

15

D3953-19 Manufactured No

100 Each 30.0000 1 1

D3953-19

Gas Spring Bracket

**

FEB 09 2017

DAS
6
8-89

Location

Loc Qty

Loc Code

ST062

10

147350

10

ST064A

20

153480

5

154207

5

154208

5

154776

5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step # : _____		QTY Effective : _____			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____						
Misidentified	☐	Past Due	☐							

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

D3953-21

Manufactured No

100

Each

34.0000

1

1

FEB 09 2017

DAS
6
9-89

D3953-21

Gas Spring Bracket

**

Location

Loc Qty

Loc Code

ST063

34

147443

9

152996

9

154213

6

154310

10

D3969-3

Manufactured No

100

Each

12.0000

1

1

FEB 09 2017

DAS
6
9-89

D3969-3

Spring (Basket Lid)

**

Location

Loc Qty

Loc Code

ST365

12

153301

12

AN3-14A

Purchased No

100

Each

110.0000

4

4

FEB 09 2017

DAS
6
9-89

AN3-14A

Bolt

**

Location

Loc Qty

Loc Code

over003

80

m134852

0

m135966

50

m136406

30

ST348

30

m135600

30

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Page 5

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

AN3-16A Purchased No

100 Each 55.0000 2 2

AN3-16A

Bolt

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

37

117441

37

ST348

18

M136044

18

AN5-17A Purchased No

100 Each 95.0000 4 4

AN5-17A

Bolt

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

20

117872

20

ST337

75

m136047

75

AN4-12 Purchased No

100 Each 77.0000 3 3

AN4-12

Bolt

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

over003

60

m136199

40

m136444

20

ST344

17

m135408

17

Thursday, January 19, 2017 11:37:26 AM

Shop Packet Print

Page 5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : _____							

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

AN310-4

Purchased

No

100

Each

77.0000

3

3

AN310-4

Nut

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

25

M127815

25

OVER007

40

M135704

0

M136295

40

ST331

12

M135999

12

3

AN310C4

Purchased

No

100

Each

81.0000

2

2

AN310C4

Nut

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

OVER007

25

M136450

25

ST331

56

M135297

21

M135895

35

2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Page 7

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

100

Each

1,821.000

6

6

MS21042L3

FEB 09 2017

Nut

Location

Loc Qty

Loc Code

FP001

100

m135945

100

GA

162

m134360

108

m135135

54

OVER007

500

M136554

500

ST303

1059

M136044

11

M136192

548

M136406

500

MS21042L5

Purchased

No

100

Each

309.0000

4

4

MS21042L5

FEB 09 2017

Nut

Location

Loc Qty

Loc Code

GA

21

m127813

21

OVER007

100

m136450

100

ST303

188

m136047

88

m136295

100

Thursday, January 19, 2017 11:37:26 AM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
		OTHER : _____							

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

MS24665-151

Purchased

No

100

Each

171.0000

3

3

MS24665-151

Cotter Pin

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

60

m128401

60

ST289

111

m135274

11

m136444

100

MS24665-300

Purchased

No

100

Each

89.0000

2

2

MS24665-300

COTTER PIN

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

28

118234

28

ST288

61

m135046

61

NAS1149F0432P

Purchased

No

100

Each

1,587.000

6

6

NAS1149F0432P

WASHER

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

ST260a

1000

M136442

1000

ST262

587

M135704

587

NAS1149F0563P

Purchased

No

100

Each

105.0000

4

4

NAS1149F0563P

Washer

**

FEB 09 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

ST262

105

m134852

105

Thursday, January 19, 2017 11:37:26 AM

Shop Packet Print

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Thursday, January 19, 2017 11:37:26 AM

Page 9

Work Order ID: 155991

155991

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 1/31/2017

Required Date: 2/1/2017

Start Qty: 1.00

Required Qty: 1.00

NAS1149F0332P

Purchased

No

100

Each

2,378.000

8

8

NAS1149F0332P

Washer

**

FEB 09 2017

Location

Loc Qty

Loc Code

GA

343

m133709

343

ST262

2035

m135948

235

m136442

1800

NAS1149C0432R

Purchased

No

100

Each

1,489.000

2

2

NAS1149C0432R

WASHER

**

FEB 09 2017

Location

Loc Qty

Loc Code

GA

373

m134676

373

ST266

1116

m135979

116

m136182

1000

DAS
6
9-89

Thursday, January 19, 2017 11:37:26 AM

Shop Packet Print

Page 9

DQA: _____ Date: _____




WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____				
Description Work Order Deviation				Disposition							
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐		☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due		☐ Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter		FAULT CATEGORY ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes		☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center		☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence	
☐ OTHER : _____											

ITEM	QTY -041	P/N	DESCRIPTION
	X	D4030-041	LONG BASKET ASSY (350)
1	1	D2530	HANDLE WELDMENT
2	2	D2535	SPRING
3	2	D2537	BUSHING
4	1	D3913-041	LONG BASKET BASE ASSY (350)
5	1	D3914-041	LONG BASKET LID ASSY (350)
6	6	D3917-3	WASHER
7	2	D3953-3	GAS SPRING STUD, LID
8	2	D3953-7	GAS SPRING SPACER
9	2	D3953-9	GAS SPRING WASHER
10	2	D3953-17	GAS SPRING SPACER
11	1	D3953-19	GAS SPRING BRACKET
12	1	D3953-21	GAS SPRING BRACKET
13	1	D3969-3	SPRING
14	4	AN3-14A	BOLT, MACHINE
15	2	AN3-16A	BOLT, MACHINE
16	3	AN4-12	BOLT, MACHINE
17	4	AN5-17A	BOLT, MACHINE
18	2	AN310C4	NUT, PLAIN, CASTELLATED
19	3	AN310-4	NUT, PLAIN, CASTELLATED
20	6	MS21042L3	NUT, SELF-LOCKING
21	4	MS21042L5	NUT, SELF-LOCKING
22	2	MS24665-300	COTTER PIN
23	3	MS24665-151	COTTER PIN
24	2	NAS1149C0432R	WASHER
25	6	NAS1149F0432P	WASHER
26	8	NAS1149F0332P	WASHER
27	4	NAS1149F0563P	WASHER



D4030-041 LONG BASKET ASSY (350)
(MESH SHOWN LOCALLY FOR CLARITY)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *D/SS991*


JAN 19 2017

RELEASED
2013-08-16

NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: 72 lbs APPROX

D	REFORMAT FOR CLARITY: PICTORIAL UPDATE TO MULTIPLE VIEWS DUE TO CHANGES IN SUB ASSEMBLIES.	AJS	13.07.18
C	QTY FOR ITEMS #30 & #31 UNDER .043 WERE MISSING (B8-1); QTY FOR ITEM #3 WAS 4 (D8-1), ONLY 2 ARE REQUIRED, AFFECTS SECTION C-C (D3-3).	MB	10.07.23
B	AN5-21A BOLT WAS AN5-19A: BOM & (D3-3)	JPH	10.04.06
A	NEW ISSUE	JPH	10.03.16
REV.	DESCRIPTION	BY	DATE
DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. D
MFG. APPR.	<i>[Signature]</i>	D4030	SHEET 1 OF 4
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

ITEM	QTY -043	P/N	DESCRIPTION
	X	D4030-043	LONG BASKET ASSY, LIGHT LID (350)
1	1	D2530	HANDLE WELDMENT
2	2	D2535	SPRING
3	2	D2537	BUSHING
4	1	D3913-041	LONG BASKET BASE ASSY (350)
5	1	D3915-041	LIGHT LID ASSY, LONG BASKET
6	6	D3917-3	WASHER
7	2	D3953-3	GAS SPRING STUD, LID
8	2	D3953-7	GAS SPRING SPACER
9	2	D3953-9	GAS SPRING WASHER
10	2	D3953-17	GAS SPRING SPACER
11	1	D3953-19	GAS SPRING BRACKET
12	1	D3953-21	GAS SPRING BRACKET
13	1	D3969-3	SPRING
14	4	AN3-14A	BOLT
15	2	AN3-20A	BOLT
16	3	AN4-12	BOLT
17	2	AN5-17A	BOLT
18	2	AN5-21A	BOLT
19	3	AN310-4	NUT, PLAIN, CASTELLATED
20	2	AN310C4	NUT, PLAIN, CASTELLATED
21	6	MS21042L3	NUT, SELF-LOCKING
22	4	MS21042L5	NUT, SELF-LOCKING
23	3	MS24665-151	COTTER PIN
24	2	MS24665-300	COTTER PIN
25	6	NAS1149F0432P	WASHER
26	4	NAS1149F0563P	WASHER
27	8	NAS1149F0332P	WASHER
28	2	NAS1149C0432R	WASHER




D4030-043 LONG BASKET ASSY, LIGHT LID (350)
(MESH SHOWN LOCALLY FOR CLARITY)

RELEASED
2013-08-16


NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: N/A
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 57 lbs APPROX

DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. D
MFG. APPR.		D4030	SHEET 2 OF 4
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			



DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. D
MFG. APPR.		D4030	SHEET 3 OF 4
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			



RELEASED
2013-08-16
AM

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO. D4030	REV. D
MFG. APPR.	<i>[Signature]</i>	SHEET 4 OF 4	
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	LONG BASKET ASSY (350)	
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	